

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: April 1, 2009 **Name:** Steven Langseder

Weather

Conditions: Overcast, 45°F

General Inspection:

Is the Milnor Street entrance secure?	(Y/N)
Is the Cottman Ave entrance secure?	<u>Yes</u>
Are there any breaches in site security in the site gate/fence?	<u>Yes</u>
If Yes, describe in detail below and mark on the attached site map.	<u>No</u>

The fence in the Courtyard along Cottman Avenue was tilted slightly toward
Cottman Avenue due to the wind. The fence was repaired during the site visit
conducted on April 1st.

Site sign remains in good condition?	<u>Yes</u>
If no, please explain:	

Are the circuit breakers locked and secured?	<u>Yes</u>
---	------------

Building 7:

Are the doors to Building 7 locked?	<u>Yes</u>
Has security for Building 7 been breached?	<u>No</u>
Is the high visibility fence and welded wire still in place at the front door?	<u>Yes</u>
Comments:	

Exclusion Zone:

Zone remains well defined (i.e., construction fence remains intact)?	<u>Yes</u>
Sheet Pile Wall remains in good condition?	<u>Yes</u>
Marine Mattresses remain covered?	<u>No</u>

If no, please specify areas that need to be addressed:

The cover on the third (as seen from the eastern return facing west)
mattress stockpile was blown from the southwestern corner of the stockpile.
The cover on the empty (not filled with stone) mattress stockpile was
partially blown from the pile. The covers were repaired on April 1st.

Are the fish warning signs still hanging?	<u>Yes</u>
--	------------

Additional Notes or Comments:

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: April 1, 2009 **Name:** Steven Langseder

Weather

Conditions: Overcast, 45°F

E&S Measures

Are there any breaches or damage to the silt fence in the Courtyard Area?	(Y/N)
If yes, please describe in detail and mark on attached site map:	<u>No</u>

Are repairs necessary?	<u>No</u>
If yes, please describe in detail and mark on attached site map:	

Are there any breaches in the Support Area?	<u>No</u>
If yes, please describe in detail and mark on attached site map:	

Are repairs necessary?	<u>No</u>
If yes, please describe in detail and mark on attached site map:	

Additional Notes or Comments:

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: April 1, 2009 **Name:** Steven Langseder

Weather

Conditions: Overcast, 45°F

E&S Measures

(Y/N)

Are there any breaches in the Exclusion Zone? No

If yes, please describe in detail and mark on attached site map:

Are repairs necessary? No

If yes, please describe in detail and mark on attached site map:

Are there any breaches in the Sheet Pile Wall Area? No

If yes, please describe in detail and mark on attached site map:

Are repairs necessary? No

If yes, please describe in detail and mark on attached site map:

Additional Notes or Comments:

Sagging silt fence observed along the western and southern perimeters of the Site was
repaired during the site inspection conducted on April 1st.

Date: April 1, 2009 **Name:** Steven Langseder
Weather
Conditions: Overcast, 45°F

Bill Burke, TtEC, and Steven Langseder, Malcolm Pirnie, Inc. performed the weekly site inspection on Wednesday, April 1, 2009.

At approximately 11:05a.m., Andy Sinclair of the Pennsylvania Department of Environmental Protection arrived on-Site. He toured the Site and expressed general satisfaction with the erosion and sediment control measures, although some portions of the silt fence are beginning to show their age. Mr. Sinclair was concerned about the area to the west of the Western Return of the sheetpile wall because of its vulnerability to potential future damage or breaches. He requested that TtEC and Malcolm Pirnie continue to monitor this location during the weekly inspections. I informed him that we would. Mr. Sinclair left the Site at approximately 11:35a.m.